



00684.003506

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)
HARUYUKI YANAGI, ET AL.) Examiner: E. Eickholt
Application No.: 10/614,065) Group Art Unit: 2854
Filed: July 8, 2003)
For: RECORDING APPARATUS) August 11, 2005
U.S. Patent No. 6,871,946 B2)
Issued: March 29, 2005)

The Honorable Commissioner of Patents
and Trademarks
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
AUG 17 2005
of Correction

REQUEST FOR
CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes and mistakes which are not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205.

08/12/2005 6871946-00000079-10614065
01 FC:1811


100.00 OP

18 2005

08/15/2005 6871946-00000006 6871946
01 FC:1811

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,



Scott D. Malpede
Attorney for Patentees
Registration No. 32,533

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SDM\mm

DC_MAIN 208144v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,871,946 B2

DATED : March 29, 2005

INVENTOR(S) : HARUYUKI YANAGI, ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 5:

Line 55, "DC" should read --CD--.

COLUMN 21:

Line 38, "Cd." should read --CD.--.

COLUMN 23:

Line 25, "DC" should read --CD--.

COLUMN 31:

Line 53, "designed" should read --designated--; and
Line 58, "is" should read --does--.

COLUMN 34:

Line 16, "12 cm Cd" should read --12 cm CD--;

COLUMN 35:

Line 45, "8 cm Cd" should read --8 cm CD--.

COLUMN 37:

Line 67, "is" (second occurrence) should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,871,946 B2

No. of add'l. copies
@ 30¢ per page



AUG 18 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,871,946 B2

DATED : March 29, 2005

INVENTOR(S) : HARUYUKI YANAGI, ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 40:

Line 24, "presence" should read --a presence--;

DC_MAIN 208150v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,871,946 B2

No. of add'l. copies
@ 30¢ per page



AUG 18 2005